

Governor

GARY HERBERT Lieutenant Governor

Department of **Environmental Quality**

Richard W. Sprott Executive Director

DIVISION OF SOLID AND HAZARDOUS WASTE Dennis R. Downs Director

December 2, 2008

Nathan Rich, Executive Director Wasatch Integrated Waste Management District 650 East Highway 193 Layton, Utah 84041

Re: November 25, 2008 Landfill Inspection

Dear Mr. Rich:

On November 25, 2008, Rob Powers with the Solid Waste Section conducted a routine inspection of the Wasatch Integrated Waste Management District landfill. The purpose of the inspection was to determine compliance with the Utah Solid Waste Permitting and Management Rules (Rules) and the landfill permit.

Enclosed is a copy of the inspection checklist and brief comments and photographs taken during the inspection. The inspection revealed that the landfill operations reviewed during the inspection were conducted within the rules and permit requirements.

The Division appreciates the efforts of the Wasatch Integrated Waste Management District staff in meeting the operating standards in the Rules. If you have any questions, please feel free to contact Rob Powers or Ralph Bohn at 538-6170.

Sincerely,

Original Document signed by Dennis R. Downs on 12/2/08

Dennis R. Downs, Executive Secretary Utah Solid and Hazardous Waste Control Board

DRD/RDP/kk

Enclosure: Inspection Photographs, Inspection Checklist

Delane McGarvey, Director, Environmental Health, Davis County Health Department c: Preston Lee, Landfill Manager, Wasatch Integrated Waste Management District

SOLID WASTE FACILITY INSPECTION REPORT CHECKLIST

UTAH DIVISION OF SOLID & HAZARDOUS WASTE

Facility Name Wasatch Integrated Waste Management Dist County Davis
Location 650 East Highway 193, Layton, Utah
Inspection Date 11/25/07 Time In 9:30 am Time Out Noon
· · · · · · · · · · · · · · · · · · ·
Announced Unannounced Weather Conditions Sunny and about 50 degrees
Inspection Goal Compliance with the permit and the rules
Facility Contact Preston Lee and Nathan Rich
Participants Preston Lee
FOLLOW UP INSPECTION NEEDED Yes No Recommended Follow Up Date
TOLLOW OF INSI ECTION NEEDED Tes No Recommended Follow of Date
(V : 1: -1 : : : : : : : : : : : : : : : : : : :
(X - indicates items reviewed) 1. PRE-INSPECTION REVIEW
☐ 1.1 Permit Review
2.14 Other
3. SIGNS REQUIRED / PROPERLY POSTED
1 oseed as you approach the search oase
□ 1.5 Facility Contacted (if announced inspection) □ 3.2 Directions & Procedure
□ 3.3 Emergency Numbers
1.6 Local Heath Contacted
■ 3.4 List of Unacceptable Materials
1.7 Other Listed on signs as you approach the facility
2. FACILITY / OPERATIONAL CONTROLS
□ 2.1 Litter
Very little if any litter at the time of my visit 4. OPERATOR / REPRESENTATIVE / EMPLOYEES 4. 1 On-site while open
Z.Z Koaus
In great shape the weather has been very dry which helps Solution 2.3 Gets Hove Operations
2.3 Gate House Operations Looked at training logs
Z 2.4 vectors
Hand held radios 5. MONITORING
\[\] \[\]
Reviewed the logs and they were complete
☑ 2.7 Fugitive Dust Control ☑ 5.2 Random Inspections Roads are water regularly to control the dust. Reviewed the logs, looked good
Roads are water regularly to control the dust. Reviewed the logs, looked good □ 2.8 Waste Inspection Area □ 5.3 Leachate
2.8 waste hispection Area
Not allowed
Not allowed
2.11 Fences, Gates, Locks, Access Control
In good shape 6. DRAINAGE / EROSION ☑ 2.12 Working Face ☑ 6.1 Water Run-on
☑ 2.12 Working Face See photos attached ☑ 6.1 Water Run-on

SOLID WASTE FACILITY INSPECTION REPORT

Date: 11/25/07 Facility Name: Wasatch Integrated Waste Management Dist	
	9.7 Final Cover
6.3 Other	
	9.8 Self Inspection (Quarterly) Reports
7. PROPER STORAGE / ISOLATION / DISPOSAL	
☐ 7.1 Special Waste	9.9 Deviation from Plans
☐ 7.2 Batteries	9.10 Permit, Permit Application and Rules Available
Recycled see photographs	
7.3 Hazardous Waste	9.11 Other
Not accepted in the landfill 7.4 Infectious Waste	
7.4 Infectious Waste	10. MONITORING / SAMPLING / ANALYSIS RECORDS
	10.1 Explosive Gas Monitoring
7.5 Thes	10.1 Explosive das Monitoring
☐ 7.6 Dead Animals	☐ 10.2 Leachate Sampling & Treatment
7.0 Dead / Hillings	10.2 Beachate Sampling & Treatment
☐ 7.7 Asbestos	☐ 10.3 Ground Water Sampling Results
☐ 7.8 Bulky Waste	10.4 Other
☐ 7.9 Contaminated Soil	
	11. SPECIAL WASTE RECORDS
	11.1 Lab Analysis Results
Ash from burn plant see attached photos	
☐ 7.11 Sludge	11.2 Manifests
Not accepted	
7.12 Other	11.3 Treatment Certification
	11.4 Paint Filter Test Results
8. COVER	
8.1 Daily - Soil	11.5 Onsite Treatment Documentation
Looked good. Toured the area were the soil is stock piled	
⊠ 8.2 Daily - Alternative	11.6 Other
8.3 Intermediate	12. SPECIAL PERMIT REQUIREMENTS
	12. 31 ECIAL 1 ERWITI REQUIREMENTS
0.41 mai	
□ 8.6 Other	□ 12.3
9. INSPECTION RECORDS	13. OTHER ITEMS
Randomly reviewed the logs for the year. Looked good.	
9.2 Gas Monitoring System	□ 13.2
	□ 13.3
57 Louis III - 1	
9.4 Daily Records	□ 13.4
Reviewed and looked great.	
9.5 Weight or Volumes	13.5
Complete	
9.6 Intermediate Cover	_
DCHW Inspector Cignature:	
DSHW Inspector Signature:	

11/25/08

Date:

DSHW Inspector Name (type or print): Rob Powers



Working face





Separating metal form the ash generated at the Energy Recovery Plant





Household Hazardous Waste is collected free of charge to the public





Used Oil is collected for recycle